# **Timber Newsletter Index**

### 150x150

Feedback on 150x150 - <u>January 2015</u> The drought uncovers some deadly sins – <u>March 2020</u> Which hardwood grading standard should I use – <u>April 2020</u>

### **3D** Printing

Introduction to 3D printing – February 2015

### 50 mm joists

A reminder - <u>February 2015</u> Deadly Sin No. 2 on the sunshine Coast– <u>April 2019</u> Stagger your screw line – <u>July 2019</u> Correct detailing does matter - <u>November 2020</u>

#### **Battens**

Simple but stunning use of battens – <u>June 2019</u> What has a Big Mac and cladding have in common – <u>December 2019</u> Fastener end distances – <u>November 2023</u> Don't span your battens too far – <u>February 2024</u>

### **Boardwalks**

Sacred site Boardwalks – <u>April 2015</u> Why do I bother – <u>June 2015</u> The Customer isn't always right – <u>November 2017</u> Lessons from a 30-year-old boardwalk – <u>December 2017</u> A boardwalk that planned to succeed– <u>March 2019</u> Please explain – <u>December 2019</u> Correct detailing does matter - <u>November 2020</u> Galvanised fasteners can be a Recipe for Disaster – <u>November 2021</u> We can be too clever (flood resilience) – <u>March 2022</u>

### **Bollards**

Bollards – Let the buyer beware – <u>October 2015</u> Canberra bollards- <u>January 2015</u> Same plans but two different products –<u>December 2015</u> Timber bollards that have not aged gracefully – <u>May 2015</u> Attractive project using eclipse bollards – <u>September 2018</u> FWPA bollard guide – <u>October 2018</u> Don't specify bollards till you read this guide – <u>November 2018</u> Spreading the word in Canberra – <u>May 2019</u> How deep do bollards have to be in the ground – <u>October 2019</u> New CPD course on bollards - <u>March 2023</u> Why do we do things that are just plain wrong – <u>April 2023</u> Plastic or timber bollards, which is better? – <u>October 2023</u>

### Books

Architectural Timber Batten Book completed – August 2015 Baptist History - February 2015 Fence images sought – September 2015 Help needed for architectural battens – May 2015 Images sought for footbridge book – <u>August 2015</u> New book being written (Architectural Timber Battens) – June 2015 New publication finalised – October 2015, – February 2016 New book on joints being written – May 2016 Contribution to French book on tropical timber – June 2016 New book on timber joints - March 2017 New guide, External Timber Furniture – September 2018 A treat for wood lovers and railway buffs – September 2020 Pre-release editions of Timber in Playgrounds available – March 2021 Why you need Bootle's Wood in Australia – July 2022 Guide to timber handrail released – December 2022 Started new guide to timber steps - March 2023 Restoring a bridge for 1/10<sup>th</sup> the cost of concrete – April 2023 You need the industry "Bible" - July 2023

### **Bridges**

Bridge inspection course - January 2015 Log Footbridges – April 2015 Large timber structures – April 2015 special edition Paint finish for external structures – June 2015 Wisdom of high design loads - May 2015 New publication being finalised – September 2015 What does a London bus have in common with my trusses?- December 2015 Large Timber structures – April 2016 special edition Covered bridges and the birth of American engineering– November 2016 Mareeba Shire turns to timber bridges over concrete -August 2017 You can build an Oscar worthy bridge – January 2018 Economic and speedy bridge replacement – July 2018 Covered bridges really work – April 2019 Pre-war but which war (40m timber bridge) January 2020 Krause bridge, a lesson in longevity – May 2020 The capabilities of external gluelam – August 2020 Another timber bridge to replace steel in Canada – October 2020 Iconic timber bridge restored (Brunswick Heads) – December 2020 Covered bridge restoration – February 2021 An Interesting handrail from the UK (sloping handrails) - July 2021 A Not so interesting handrail from Australia (poorly done)- July 2021 Poor Timber Design Needed a Fast Repair (laminated beam) – August 2021 35 metre span timber bridge in Canada – February 2022 A problematic timber design – August 2022

### **Buildings**

Another great project from architects of Arcadia – June 2020

Another one of my follies – <u>October 2020</u> Inspecting the world's largest timber structure – <u>January 2024</u>

# **Case Histories - Bad**

Dangerous Canberra Deck - <u>January 2015</u> Dangerous Canberra deck finally made safe – <u>January 2017</u> Why do I bother (Re boardwalk) - <u>June 2015</u> Timber bollards that have not aged gracefully – <u>May 2015</u> Problematic timber bridge design – <u>August 2022</u> Step case history from step guide – <u>May 2023</u> A creative footing solution – <u>February 2024</u>

### **Case Histories - Good**

Largest timber church in Australia – June 2016 Salt storage shed East Windsor (USA) using shearplates – February 2017 A decent garden wall – March 2017 Rothoblass headquarters Italy using cross laminated timber – March 2017 Tree of Knowledge memorial Barcaldine – April 2017 Mareeba Shire turns to timber bridges over concrete - August 2017 Kurata Co in Japan excels with spotted gum – April 2018 An early boardwalk revisited (Toohey Forest) – May 2018 Another great structure at Toohey Forest Park, Part 1– June 2018 Another great structure at Toohey Forest Park, Part 2– July 2018 Are you purchasing for durability (Brisbane Botanic Garden) – October 2018 Another one of my follies (bell tower Dalby) - November 2020 Domestic deck at The Gap - February 2021 Ports North Playground – Cairns – March 2021 Spotted gum seats in Budapest – May 2021 Queenslander houses – May 2021 Deck replacement – Gold Coast – October 2021 Two bell towers compared (Dalby and Charters Towers) – November 2021 We can be too clever (flood resilience) - March 2022 Spotted gum viewing deck in Japan – June 2022 Something good in Canberra (pergola) – <u>August 2022</u> Refurbished deck at Samford – December 2022 All Hallows school deck – May 2023 Uluru drone show boardwalk and deck – June 2023 Amazing spotted gum deck in Japan – August 2023 Handrail on refurbished footbridge – October 2023 Sunpu's workshop, Takumijuku (Japan) – December 2023 Case History – Mayes Canal Boardwalk – April 2024

### Cladding

What have a Big Mac and cladding have in common – <u>December 2019</u> Whoever thought plastic was a good idea – <u>September 2019</u> Timber cladding in multi-story buildings – <u>September 2020</u>

# Cocowood

Cocowood, is it any good? - October 2016

### Connections

World's largest timber structure – <u>March 2016</u> Salt storage shed East Windsor (USA) using shearplates – <u>February 2017</u>

#### **Consultancy Services**

Expert witness – <u>November 2015</u> Ted is speaking on battens for Timber Queensland – <u>January 2016</u> Gold Coast City Council builds an outstanding deck – <u>July 2017</u> Consultancy services through BCRC – <u>August 2017</u> The importance of Timber Grading – <u>December 2017</u> Footbridge inspections – <u>August 2018</u> Grading timber in a Venetian palace – <u>November 2018</u> Why you need to engage a timber consultant even if it's not me – <u>November 2019</u>

### **Cypress**

The difference between pine hardwood and cypress – September 2016

### **Deck Collapses**

Another deck collapse – <u>December 2017</u> Another deck fatality before the coroner – <u>June 2020</u>

### **Decks - Commercial**

Deckwood – new manufacturing arrangements – January 2016 Ted has finally found something more durable than Deckwood – November 2015 Width to thickness ratio - - November 2016 How long will a timber deck last - March 2017 Joining decks on commercial decking – June 2017 Choosing timber by colour - July 2017 Gold Coast City Council builds an outstanding deck – July 2017 What decking profile us that – July 2017 Should decks be load limited – November 2017 It is a good idea to pre-oil your deck – November 2017 Avoiding trip hazards in decking – April 2020 Are your decks self-cleaning – April 2020 Why you don't use dressed face decking externally – August 2018 Putting form before function – June 2019 Spotted gum decks in Japan – May 2020 This is why you do things correctly – July 2020 Japanese tea garden deck – July 2020 Why don't we check – <u>August 2020</u> Deck replacement – Gold Coast – October 2021 What decking oil should I use – May 2022 Deckwood available for vehicle decking – June 2022 Amazing spotted gum deck in Japan – August 2023 Case History – Mayes Canal Boardwalk – April 2024

### **Decks - Domestic**

How to ensure correct verandah joist life – August 2015 Nail or screw domestic decking – April 2015 Some basics – November 2015 How to Protect and keep your deck looking good – June 2017 Choosing timber by colour - July 2017 Should decks be load limited – November 2017 It is a good idea to pre-oil your deck – <u>November 2017</u> Why you don't use dressed face decking externally – August 2018 A Dear Lord Give my strength moment – January 2019 Updated Timber Queensland Decking Guides - September 2019 LVL and common sense (USA deck collapse) – February 2020 Spotted gum decks in Japan – May 2020 Another deck fatality before the coroner – June 2020 Beware F17 KD specification – September 2021 What decking oil should I use – May 2022 Refurbished deck at Samford (LifePlus) - December 2022 All hallows School Lifeplus – May 2023 Timber decks close to the ground – December 2023

#### **Decks - Plastic**

Plastic decking with termites – <u>September 2016</u> It seemed a good idea at the time – <u>August 2017</u> Another failed plastic deck – <u>April 2018</u> Timber, is there a better product – <u>May 2019</u> Whoever thought plastic was a good idea – <u>September 2019</u>

### **Durability**

Thermally modified timber - January 2015 Designing for the local climate – <u>November 2015</u> Non durable timber has lasted more than 100 years – <u>May 2016</u> Deadly Sin No. 7, Getting Durability ratings Right – <u>February 2019</u> Oils ain't oils and wood ain't wood – <u>February 2019</u> National centre for timber durability – <u>June 2020</u> This is why I disapprove of using Oregon pine externally – <u>July 2020</u> A quick look at some common species – <u>October 2020</u> Another one of my follies (Kangaroo Point) – <u>October 2020</u> Another one of my follies (Bell tower Dalby) – <u>November 2020</u> Beware F17 KD specification – <u>September 2021</u> Two bell towers compared (Dalby and Charters Towers) – <u>November 2021</u> We can be too clever (flood resilience) – <u>March 2022</u> Is Oregon durable – <u>May 2023</u> Care needed with kwila/merbau – <u>November 2023</u>

#### **Engineered** Timber

Using laminated beams externally – <u>September 2015</u> Using LVL beams externally – <u>September 2015</u> Rothoblass headquarters Italy using cross laminated timber – <u>March 2017</u> Timber library in remote Solomon Islands – <u>May 2017</u> Mareeba Shire turns to timber bridges over concrete -<u>August 2017</u> Be careful choosing your species – <u>October 2017</u>

### **Fences – Domestic**

Fence images sought – <u>September 2015</u>, <u>October 2015</u> Timber fence book finalised – <u>January 2016</u> Everything fencing – <u>April 2016</u> Be careful with ply fences – <u>September 2017</u> Be careful choosing your species – <u>October 2017</u> A striking spotted gum fence in Japan – <u>March 2021</u> How not to do a fence – <u>April 2022</u> Horse fencing – <u>November 2023</u>

### **Fasteners**

Nail or screw domestic decking – April 2015 When to use stainless bolts and brackets – July 2015 Galvanised bolts more variable than timber – June 2016 Problems looming with self drilling screws – June 2016 More on galvanised bolts - July 2016 More on galvanised bolts - August 2016 More on galvanised bolts – September 2016 Choosing the correct decking fastener part 1 – November 2016 Choosing the correct decking fastener part 2 – December 2016 Choosing the correct decking fastener part 3 – January 2017 Corroding galvanised joist hangers – November 2016 Tube nuts – December 2016 Salt storage shed East Windsor (USA) using shearplates – February 2017 A Dear Lord Give my strength moment – January 2019 Stagger your screw line – July 2019 Why don't we check - August 2020 Vandal resistant fasteners – February 2021 Tell me how to detail it Correctly (steel corroding at stainless bolt) – April 2021 Tell me how to detail it Correctly replies (steel corroding at stainless bolt) – June 2021 Staying one jump ahead of the idiots (need for special nuts) – June 2021 Galvanised fasteners can be a Recipe for Disaster - November 2021 End and edge clearances of bolts – March 2022 Fastening domestic decking to steel joists – February 2023 Recommended screw for fixing Deckwood to steel – August 2023 Fastener end distances – November 2023

### Flooring

A real-life ghost story – <u>March 2015</u> Controlling the gaps in T&G flooring – <u>March 2018</u> When is kiln dried not kiln dried – <u>January 2019</u> A reminder about narrow floorboards – <u>September 2019</u> Queenslander houses – <u>May 2021</u> Using T&G flooring as decking – <u>February 2023</u>

# Finishing

A real-life ghost story – <u>March 2015</u> Paint finish for external structures – <u>June 2015</u> Keep Your Deck Looking Good & Protected – <u>June 2017</u> It is a good idea to pre-oil your deck – <u>November 2017</u> Don't do silly things with timber – <u>November 2019</u> Choice of paint colour is important – <u>December 2020</u> Tell me how to detail it correctly replies (painted steel corroding at stainless bolt) – <u>June 2021</u> What decking oil should I use – <u>May 2022</u>

### Fire

Fire retardant coatings code of practice released – <u>June 2018</u> A lesson from the recent bushfires (CCA and fire) – <u>January 2020</u> Feedback on a lesson from recent bushfires – <u>February 2020</u>

### Furniture

Be careful choosing your species – <u>October 2017</u> Writing a book on external furniture – <u>November 2017</u> External timber furniture, all you need to know – <u>October 2018</u>

### Grading

A reminder about sleepers – <u>March 2016</u> How to measure end splits – <u>March 2016</u> Limitations of visual grading – <u>January 2018</u> Don't specify timber by F grades – <u>August 2018</u> Which hardwood grading standard should I use – <u>April 2020</u> A philosophical question prompted by Kortney and Dave – <u>January 2021</u> Losing confidence in timber is so unnecessary – <u>September 2021</u> Beware F17 KD specification – <u>September 2021</u> Deck replacement – Gold Coast – <u>October 2021</u> How not to do a fence – <u>April 2022</u> New hardwood requires care in its specification – <u>June 2022</u> Guide to timber handrail released – <u>December 2022</u> Never specify sleepers – <u>June 2023</u> A broken heart in one so young – <u>August 2023</u>

### Handrail

Detailing a commercial handrail – June 2019 An Interesting handrail from the UK (sloping handrails) – July 2021 A Not so interesting handrail from Australia (poorly done)– July 2021 New CPD Course on handrail – August 2021 Losing confidence in timber is so unnecessary – September 2021 Fixing handrails – October 2021 Correct use of LOSP Treated Handrail - January 2022 Do end sealants actually work – February 2022 A suggested handrail bracket – February 2022 Specification for commercial handrail – July 2022 Guide to timber handrail released – December 2022 Handrail on refurbished footbridge – <u>October 2023</u> Why is this handrail 6.4m long? - <u>March 2024</u>

### Hardware

Fencing brackets – <u>February 2016</u> Corroding galvanised joist hangers – <u>November 2016</u> Salt storage shed East Windsor (USA) using shearplates – <u>February 2017</u> Stump caps – <u>March 2017</u>

# Heart in timber

Feedback on 150x150- <u>January 2015</u> The difference between pine hardwood and cypress – <u>September 2016</u> Using heart-in timber – <u>February 2017</u> Stump caps – <u>March 2017</u> Tree of Knowledge memorial Barcaldine – <u>April 2017</u> Using heart in timber correctly – <u>April 2020</u> Losing confidence in timber is so unnecessary – <u>September 2021</u>

# History

The two Henry Fords of housing (part 1) - <u>August 2016</u> The two Henry Fords of housing (part 2) – <u>September 2016</u> Trusses a brief history – <u>October 2016</u> Largest timber gable truss in Australia – <u>December 2016</u> Sons of Gwalia headframe restoration options – <u>April 2017</u>

# **Incised timber**

Incised Timber - <u>November 2020</u> Feedback on incised timber – <u>December 2020</u> Feedback on Recognising well treated sleepers – <u>February 2024</u>

# International

Brief trip to the Philippines – <u>September 2016</u> Cocowood, is it any good? – <u>October 2016</u> Rothoblass headquarters Italy using cross laminated timber – <u>March 2017</u> Timber library in remote Solomon Islands – <u>May 2017</u> Cyclone and earthquake resistant building in Solomons – <u>October 2018</u> Spotted gum decks in Japan – <u>May 2020</u> Japanese tea garden deck – <u>July 2020</u> Spotted gum projects in Japan – <u>September 2020</u> Spotted gum viewing deck in Japan – <u>June 2022</u> Amazing spotted gum deck in Japan – <u>August 2023</u>

### **Joints**

Tamedia building in Switzerland – <u>May 2016</u> Galvanised bolts more variable than timber – <u>June 2016</u> Problems looming with self-drilling screws – <u>June 2016</u> Tamedia building, Zurich – <u>August 2016</u>

# Joists

Predrilling joists for screws is critical – <u>February 2018</u> How not to do a timber joint – <u>August 2018</u> A reminder about steel joists – <u>November 2018</u> This may make steel joists work – <u>December 2018</u> You can Make Steel Joists Work – <u>January 2019</u> Deadly Sin No. 2 on the sunshine Coast– <u>April 2019</u> Don't do silly things joining timber – <u>October 2019</u> Correct detailing does matter - <u>November 2020</u> Beware F17 KD specification – <u>September 2021</u> Fastening domestic decking to steel joists – <u>February 2023</u>

### Laminated timber

Pre-war but which war (40m laminated timber bridge) <u>January 2020</u> Don't do silly things with laminated timber – <u>October 2019</u> Poor Timber Design Needed a Fast Repair (laminated beam bridge) – <u>August 2021</u>

# LVL

LVL and common sense (USA deck collapse) – February 2020

### **Moisture Content**

UTAS Want Your Moisture Content Story – December 2020

# **Paint and Oils**

What brand paint should I use – July 2016 Lui the wood turner is a fan of Tanacoat – October 2016 Keep Your Deck Looking Good & Protected – June 2017 It is a good idea to pre-oil your deck – November 2017 Choice of paint colour is important – December 2020 What paint brand should I specify – April 2022 What decking oil should I use – May 2022 Tanacoat or Tanacare – February 2024

### Pests of timber

Identifying lyctus attack – January 2018

### Pine

The difference between pine hardwood and cypress – <u>September 2016</u> Never purchase treated pine on price – <u>August 2019</u> Is Oregon durable – <u>May 2023</u>

### **Plastic Decking**

See decking – Plastic Timber, is there a better product – <u>May 2019</u> Whoever thought plastic was a good idea – <u>September 2019</u>

# Playgrounds

Kim Bowman Music – June 2017

Rethinking Robinia playground equipment – <u>December 2018</u> Use of Larch in Australia – <u>May 2019</u> Wishful thinking verse planning to succeed – <u>July 2019</u> The perils of reverse engineering – <u>December 2019</u> Most skilled spotted gum project I have ever seen – <u>July 2020</u> Only trust your mother – <u>August 2020</u> Playground timber – progress and request for images - <u>November 2020</u> Timber in playgrounds (Broadwater project) - <u>January 2021</u> Vandal resistant fasteners – <u>February 2021</u> Ports North Playground – Cairns – <u>March 2021</u> Pre-release editions of Timber in Playgrounds available – <u>March 2021</u> Text finalised for Timber in Playground guide – <u>June 2021</u> Example of why you need the playground guide – <u>January 2022</u> Bradbury Park Playspace – <u>July 2023</u>

#### Plywood

Be careful with ply fences – <u>September 2017</u> New book on plywood – <u>October 2017</u>

#### **Posts**

Hardwood posts in concrete – February 2016 Lui the wood turner is a fan of Tanacoat (turned posts) – October 2016 Stump caps – March 2017 How not to install a post – April 2017 Something else that seemed a good idea – August 2017 Your design sins will find you out, Part 1- May 2018 Your design sins will find you out, Part 1- June 2018 Deadly Sin No 6 at Jimna Fire Tower – March 2019 A lesson from the recent bushfires – January 2020 Feedback on a lesson from recent bushfires – February 2020 The drought uncovers some deadly sins – March 2020 Lay your design sins at the foot of the cross (revisited) - June 2021 Basic error with post supports - January 2022 Why do we do things that are just plain wrong – April 2023 Guidelines for installing gal posts in concrete – April 2023 Groundline special edition – September 2023 Post size requirements - September 2023 Timber house stumps – <u>September 2023</u> Lay your design sins at the foot of the cross (revisited again) – September 2023 Steel posts – September 2023 A creative footing solution – February 2024 H5 treated pine without CCA – April 2024

### **Projects**

Tamedia building, Zurich – <u>August 2016</u> A striking spotted gum fence in Japan – <u>March 2021</u> Waaje Fire Tower Refurbishment – <u>April 2021</u>

### **Recycled timber**

Recycled timber – Political Correctness – <u>April 2016</u> Is recycled timber seasoned – <u>October 2017</u> A good use of recycled timber – <u>February 2020</u>

#### Sapwood

Considering sapwood in your design - December 2021

#### Seats

This seat suits all age groups- <u>April 2019</u> Spotted gum seats in Budapest - <u>May 2021</u>

### **Shelters**

The perils of reverse engineering – <u>December 2019</u> Shelter shed design service – <u>August 2021</u>

#### **Sleepers**

A reminder about sleepers – <u>March 2016</u> Concrete or timber sleepers – <u>July 2016</u> A decent garden wall – <u>March 2017</u> Jack has a rant about dodgy treatment – <u>May 2017</u> Guide to Timber Garden Retaining walls – <u>November 2017</u> Should have used concrete not timber – <u>August 2019</u> Never specify sleepers – <u>June 2023</u> Recognising correctly treated sleepers – <u>January 2024</u> Feedback on Recognising well treated sleepers – <u>February 2024</u>

### Slip resistance

Putting form before function – June 2019

### **Standards**

Standards you can drive a bus through – <u>March 2015</u> Feedback on deficient standards – <u>June 2015</u> Forest red gum – something I just noticed – <u>August 2015</u> Revised standard AS/NZS 1170.2 released - <u>August 2016</u> A quick look at some common species – <u>October 2020</u> A Rose by any Other Name Might be Lemon (species names) – April 2021

### **Steps**

Specification for step treads – <u>July 2022</u> Case history (bad) from step guide – <u>May 2023</u>

#### Sundry

Inspect research Facilities – <u>June 2015</u> Know a decent door supplier – <u>July 2019</u> I found a decent door supplier – <u>August 2019</u> A fair question about purchasing on price – <u>November 2019</u> A Specification tool that is desperately needed – <u>September 2020</u> Is spotted gum the cure for covid? (piggery slats) – <u>March 2021</u> Calculating the weight of timber – <u>August 2021</u> Horse fencing– <u>November 2023</u>

#### **Timber Construction**

Where is Timber Construction headed - May 2015
World's largest timber structure - March 2016
Large Timber structures - April 2016 special edition
Large Timber structures follow up - April 2016
Non-durable timber has lasted more than 100 years - May 2016
They are not using shipping containers, are they? - August 2016
Largest timber gable truss in Australia - December 2016
Salt storage shed East Windsor (USA) using shearplates - February 2017
The age of the plyscraper - March 2018
Protect your top surface - May 2018
Another one of my follies - October 2020

### **Timber Queensland**

Report on Feb 2016 Seminar – February 2016

#### **Timber Research**

The state of Timber research in Australia – <u>May 2016</u> The state of Timber research in Australia – <u>June 2016</u> The state of Timber research in Australia – <u>July 2016</u> National Centre for Timber durability – <u>November 2018</u>

#### **Timber Structures**

World's largest timber structure – <u>March 2016</u> Large Timber structures – <u>April 2016</u> special edition Large Timber structures follow up – <u>April 2016</u> Non durable timber has lasted more than 100 years – <u>May 2016</u>

#### Treatment

Decay in treated pine – <u>December 2015</u> Decay in treated pine – <u>January 2016</u> Why so hard to do the right thing - – <u>January 2016</u> Jack has a rant about dodgy treatment – <u>May 2017</u> When is H3 not H3? <u>May 2017</u> A reminder about pine – <u>July 2017</u> Cairns Regional Council sets the standard for preservation – <u>September 2017</u> How to confirm correct treatment has been achieved – <u>December 2017</u> Timber treatments do not repel insects – <u>February 2018</u> Timber, is there a better product – <u>May 2019</u> Guide for exercising due diligence with treated timber – <u>November 2019</u> Lesson from a recent bushfire (CCA and fire) – <u>January 2020</u> LVL and common sense – <u>February 2020</u> Another one of my follies (Bell tower Dalby) – <u>November 2020</u> Update to new timber preservation guide for free – <u>January 2021</u> Considering sapwood in your design - <u>December 2021</u> Correct use of LOSP Treated Handrail - <u>January 2022</u> What do the numbers on a treatment tag mean? – <u>January 2024</u> H5 treated pine without CCA – <u>April 2024</u>

### Unclasifiable

A mortgage broker that helped us – February 2016 How to get people to specify your product – February 2016 What do you do with a good idea – February 2016 An accountant that really helped us – May 2016 Sons of Gwalia headframe restoration options – April 2017 Book on the history of saws – February 2017 A treat for wood lovers and railway buffs – September 2020 Is spotted gum the cure for covid? (piggery slats) – March 2021 The Olympics of materials – July 2021 Design decision making matrix is needed – August 2022 Glad to help a young engineer with her master's degree - March 2023 Something for lovers of concrete - March 2023

### Verandahs

See Decks Domestic

### **Wood Solutions**

New guide on mid rise developments released – <u>October 2016</u> Span chart software – <u>February 2017</u> Guide to Timber Garden Retaining walls – <u>November 2017</u> New publication on slip resistance – <u>December 2018</u> Guide to Wood Construction Systems – <u>January 2019</u>

### **Wood Encouragement Policy**

A wood encouragement policy is a mixed blessing – <u>August 2017</u> A wood encouragement policy, what is needed – <u>August 2017</u>